



FIRE EXTINGUISHER MAINTENANCE REPORT

Customer Name	62 Deighton Road
Site Address	62 Deighton Road, Huddersfield HD2 1LS
Job / Order Number	SFE3166

List of devices on site		6 Litre Foam, 2kg CO2, Fire Blanket	
Type	Size	Total on site	Total Serviced
Water	9L		
	6L		
	3L		
Foam	9L		
	6L	2	2
	3L		
	2L		
Wet Chemical	9L		
	6L		
	2L		
	3L		
Dry Powder	9kg		
	6kg		
	4kg		
	3kg		
	2kg		
	1kg		
CO2	5kg		
	2kg	4	4

Fire Blanket		2	2
--------------	--	---	---

Parts Fitted	Anti-tamper tags	Safety Clips or Pins	Guage Test & Date Dot	New Hose/Head /Horn	Extinguisher Disposal	ID Sign	Fix to Wall
Quantity	6		2				

NOTES	All fire extinguishers have been serviced to BS5306-3
Not serviced reason	Nil
Summary	FULL SERVICE OF FIRE EXTINGUISHERS CARRIED OUT HOWEVER SOME REPLACEMENTS ARE REQUIRED AS SET OUT BELOW
Replacements & Locations	1 X FE-002 staff office
Other Information	Nil
Repairs & replacement parts NOT covered by warranty, necessary during our visit will be charged extra, subject to client's instruction to proceed, or a written estimate will be submitted for extra works.	

Print Name (IFS)	(09) Rowan Procter	Print Name (cust)	Enzo Nawaz
Date	Signed for IFS	Service Rating	Signed for Customer
15/12/2025	(09) Rowan Procter 	★★★★★	